

VR-Checkliste F/A-18C Waffen 1

Ungelenkte Raketen

- MASTER ARM
- MODE A/G
- DDI SMS
- PB 10S / 68S etc.
- PB CCIP
- PB SGL / SAL as req.
- PB GUN as req.
- AIM - IN RNG - SHOOT

Ungelenkte Bomben

- MASTER ARM
- MODE A/G
- DDI SMS
- PB 82B / RE / 83B etc.
- PB CCIP
- MFUZE NOSE
- PB UFC
- QTY - Zahlen - ENT
- MULT - Zahlen - ENT
- INT - Zahlen - ENT
- AIM DIL – DIVE
- CCIP CROSS / RELEASE
- F6 as req.

Bordkanone Luft/Boden

- MASTER ARM
- MODE A/G
- DDI SMS
- PB GUN
- PB CCIP
- PB HI / LO as req.
- AIM - IN RNG - SHOOT

Bordkanone Luft/Luft

- MASTER ARM
- RADAR OFF
- A/A GUNS
- DDI SMS
- PB HI / LO as req.
- AIM - SHOOT

Flügelspannweite

- PB UFC
- WSPN - Zahlen - ENT

VR-Checkliste F/A-18C Waffen 1

Sidewinder

- IRCOOL NORM
- RADAR OFF
- MASTER ARM
- WEAPON SELECT
SIDEWINDER
- Check MASTER MODE
A/A
- DDI SMS
- UNCAGE as req.
- BORESIGHT
- CAGE as req.
- FIRE

Gegenmaßnahmen

Bypass

- MASTER ARM
- DISPENSER BYPASS
- As req.
 - FLARE: DISP AFT
 - CHAFF: DISP FWD

Gegenmaßnahmen

vorbereiten

- MASTER ARM
- DDI EW
- DISPENSER ON
- SF TEST - PBIT GO - STBY
- PB ALE-47
- PB MODE MAN 1

Manuelle Programme

- PB MODE MAN X
- PB ARM
- PB CHAF – SET CHAF
- PB FLAR – SET FLAR
- PB RPT – SET RPT
- PB INT – SET INT
- PB SAVE!!!

MAN 1

CHAFF	FLARE	OTH1	OTH2	RPT	INT
0	2	0	0	3	0.50

MAN 5

CHAFF	FLARE	OTH1	OTH2	RPT	INT
2	0	0	0	4	1.50

MAN 2

CHAFF	FLARE	OTH1	OTH2	RPT	INT
0	1	0	0	10	1.00